




Left Plot w/ Pics

505-341-0109

| | | | | | |
|-----------------------------------|----------------------------------|-----------------------------------|------------------------------------|--------------|---------------------------------------|
| Pipe ID L13-5 | City | Street CLOVER LN 2210 E | Shape | Map #1 | Basin |
| US Manhole L13-5 | Section Length 72.022 | Year Laid | Material CON | Section Type | |
| DS Manhole L13-4 | Inspected Length 284.4 | Year Renewed | Depth US 9.8 | Depth DS | Joint Leng... Diameter 8 |
| Cleaned | Situation | | Reason | | |
| Date 20170224 | Clean Date | Weather | | Remark | |
| Start Time 14:13 | | | | | |
| Operator STEVEN | Customer | Truck 4165 | Inspection Dir. UPSTREAM | Info | |
| Operator Comment | P.O. Number | Present | Flow Control | Camera | |




L13-4

Distance: Pos: Val 1 / 2 : % : Gallons:


| | | | | | |
|---|---------|--|--|--|--|
| Code: TIBD | 0.0 ft. | | | | |
| Observation: Inspection Begins at Downstream MH | | | | | |
| Remarks: | | | | | |



| | | | | | |
|-----------------------------|----------|---|--|--|--|
| Code: CLV | 59.7 ft. | 3 | | | |
| Observation: Lateral Active | | | | | |
| Remarks: | | | | | |



| | | | | | |
|-----------------------------|-----------|---|--|--|--|
| Code: CLV | 118.8 ft. | 3 | | | |
| Observation: Lateral Active | | | | | |
| Remarks: | | | | | |



| | | | | | |
|-----------------------------|-----------|---|--|--|--|
| Code: CLV | 123.2 ft. | 9 | | | |
| Observation: Lateral Active | | | | | |
| Remarks: | | | | | |



| | | | | | |
|-----------------------------|-----------|---|--|--|--|
| Code: CLV | 151.8 ft. | 9 | | | |
| Observation: Lateral Active | | | | | |
| Remarks: | | | | | |



| | | | | | |
|---|-----------|--|--|--|--|
| Code: TIEU | 284.4 ft. | | | | |
| Observation: Inspection Ends at Upstream MH | | | | | |
| Remarks: MED DETERIATION THROUGHOUT LINE | | | | | |



L13-5




Scaled Plot

505-341-0109

| | | | | | |
|-----------------------------------|----------------------------------|-----------------------------------|------------------------|--------------|---------------------------------------|
| Pipe ID L13-5 | City | Street CLOVER LN 2210 E | Shape | Map #1 | Basin |
| US Manhole L13-5 | Section Length 72.022 | Year Laid | Material CON | Section Type | |
| DS Manhole L13-4 | Inspected Length 284.4 | Year Renewed | Depth US 9.8 | Depth DS | Joint Leng... Diameter 8 |

| | | | | | |
|----------------------------|-------------|----------------------|------------------------------------|--------|--|
| Cleared | | Situation | | Reason | |
| Date 20170224 | Clean Date | Weather | | Remark | |
| Start Time 14:13 | | | | | |
| Operator STEVEN | Customer | Truck 4165 | Inspection Dir. UPSTREAM | Info | |
| Operator Comment | P.O. Number | Present | Flow Control | Camera | |



* = clock positions adjusted automatically for reverse inspection

Scale: 1:350