




### Left Plot w/ Pics

505-341-0109

Pipe ID <b>N120-48</b>	City	Street <b>WANDER LN 2780 E</b>	Shape	Map #1	Basin
<b>US Manhole</b> <b>N120-48</b>	Section Length <b>57.346</b>	Year Laid	Material <b>CON</b>	Section Type	
<b>DS Manhole</b> <b>N120-47</b>	Inspected Length <b>198</b>	Year Renewed	Depth US <b>12</b>	Depth DS	Joint Leng... Diameter <b>8</b>
Cleaned	Situation		Reason		
Date <b>20181019</b>	Clean Date	Weather		Remark	
Start Time <b>13:28</b>					
Operator <b>CODY</b>	Customer	Truck <b>4161</b>	Inspection Dir. <b>Upstream</b>	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-47

Distance: Pos: Val 1 / 2 : % : Gallons:



Code: TIBD 0.0 ft. Observation: Inspection Begins at Downstream MH  
Remarks:



Code: CLV 33.6 ft. 9 Observation: Lateral Active  
Remarks:



Code: CLV 104.6 ft. 9 Observation: Lateral Active  
Remarks:



Code: TIEU 198.0 ft. Observation: Inspection Ends at Upstream MH  
Remarks:

N120-48




### Scaled Plot

505-341-0109

Pipe ID <b>N120-48</b>	City	Street <b>WANDER LN 2780 E</b>	Shape	Map #1	Basin
<b>US Manhole</b> <b>N120-48</b>	Section Length <b>57.346</b>	Year Laid	Material <b>CON</b>	Section Type	
<b>DS Manhole</b> <b>N120-47</b>	Inspected Length <b>198</b>	Year Renewed	Depth US <b>12</b>	Depth DS	Joint Leng... Diameter <b>8</b>

Cleared		Situation		Reason	
Date <b>20181019</b>	Clean Date	Weather		Remark	
Start Time <b>13:28</b>					
Operator <b>CODY</b>	Customer	Truck <b>4161</b>	Inspection Dir. <b>Upstream</b>	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



\* = clock positions adjusted automatically for reverse inspection