




Left Plot w/ Pics

505-341-0109

Pipe ID N120-47	City	Street WANDER LN 2700 E	Shape	Map #1	Basin
US Manhole N120-47	Section Length 31.154	Year Laid	Material CON	Section Type	
DS Manhole N120-45	Inspected Length 143.4	Year Renewed	Depth US 11.5	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20181019	Clean Date	Weather		Remark	
Start Time 13:55					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-47

Distance: Pos: Val 1 / 2 : % : Gallons:



Code: TIBU	0.0 ft.				
Observation: Inspection Begins at Upstream MH					
Remarks:					



Code: CLV	68.1 ft.	9			
Observation: Lateral Active					
Remarks:					



Code: CLV	106.8 ft.	3			
Observation: Lateral Active					
Remarks:					



Code: TIED	143.4 ft.				
Observation: nspection Ends at Downstream MH					
Remarks:					

N120-45




Scaled Plot

505-341-0109

Pipe ID N120-47	City	Street WANDER LN 2700 E	Shape	Map #1	Basin
US Manhole N120-47	Section Length 31.154	Year Laid	Material CON	Section Type	
DS Manhole N120-45	Inspected Length 143.4	Year Renewed	Depth US 11.5	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20181019	Clean Date	Weather		Remark	
Start Time 13:55		Truck 4161	Inspection Dir. Downstream	Info	
Operator CODY	Customer	Present	Flow Control	Camera	
Operator Comment	P.O. Number				



* = clock positions adjusted automatically for reverse inspection