




Left Plot w/ Pics

505-341-0109

Pipe ID N120-44	City	Street VALLEY VIEW AVE 481...	Shape	Map #1	Basin
US Manhole N120-44	Section Length 66.551	Year Laid	Material CON	Section Type	
DS Manhole N120-144	Inspected Length 199.3	Year Renewed	Depth US 8.5	Depth DS	Joint Leng... Diameter 8
Cleaned		Situation		Reason	
Date 20181022	Clean Date	Weather		Remark	
Start Time 10:33					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-44

Distance: Pos: Val 1 / 2 : % : Gallons:

	Code: TIBU	0.0 ft.					
Observation: Inspection Begins at Upstream MH							
Remarks:							
	Code: CLV	27.9 ft.	9				
Observation: Lateral Active							
Remarks:							
	Code: CLV	31.8 ft.	3				
Observation: Lateral Active							
Remarks:							
	Code: CLV	107.3 ft.	3				
Observation: Lateral Active							
Remarks:							
	Code: CLV	171.0 ft.	9				
Observation: Lateral Active							
Remarks:							
	Code: YCC	173.6 ft.	1 - 2				
Observation: Crack Circumferential							
Remarks:							
	Code: CLV	174.8 ft.	3				
Observation: Lateral Active							
Remarks:							



Left Plot w/ Pics

505-341-0109


Pipe ID N120-44	City	Street VALLEY VIEW AVE 481...	Shape	Map #1	Basin
US Manhole N120-44	Section Length 66.551	Year Laid	Material CON	Section Type	
DS Manhole N120-144	Inspected Length 199.3	Year Renewed	Depth US 8.5	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20181022	Clean Date	Weather		Remark	
Start Time 10:33					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



Code: TIED 199.3 ft.

Observation: nspection Ends at Downstream MH

Remarks:



N120-144




Scaled Plot

505-341-0109

Pipe ID N120-44	City	Street VALLEY VIEW AVE 481...	Shape	Map #1	Basin
US Manhole N120-44	Section Length 66.551	Year Laid	Material CON	Section Type	
DS Manhole N120-144	Inspected Length 199.3	Year Renewed	Depth US 8.5	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20181022	Clean Date	Weather		Remark	
Start Time 10:33					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:250