




### Left Plot w/ Pics

505-341-0109

|                                      |                               |                      |                                      |              |                           |
|--------------------------------------|-------------------------------|----------------------|--------------------------------------|--------------|---------------------------|
| Pipe ID<br><b>N120-191</b>           | City                          | Street               | Shape                                | Map #1       | Basin                     |
| <b>US Manhole</b><br><b>N120-191</b> | Section Length                | Year Laid            | Material                             | Section Type |                           |
| <b>DS Manhole</b><br><b>N120-36</b>  | Inspected Length<br><b>64</b> | Year Renewed         | Depth US                             | Depth DS     | Joint Leng...<br>Diameter |
| Cleaned                              | Situation                     |                      | Reason                               |              |                           |
| Date <b>20181022</b>                 | Clean Date                    | Weather              |                                      | Remark       |                           |
| Start Time <b>10:55</b>              |                               |                      |                                      |              |                           |
| Operator<br><b>CODY</b>              | Customer                      | Truck<br><b>4161</b> | Inspection Dir.<br><b>Downstream</b> | Info         |                           |
| Operator Comment                     | P.O. Number                   | Present              | Flow Control                         | Camera       |                           |



N120-191

Distance: Pos: Val 1 / 2 : % : Gallons:



|   |         |  |  |  |  |
|---|---------|--|--|--|--|
| Code: TIBU                                    | 0.0 ft. |  |  |  |  |
| Observation: Inspection Begins at Upstream MH |         |  |  |  |  |
| Remarks:                                      |         |  |  |  |  |



|                                 |         |        |  |  |  |
|---------------------------------|---------|--------|--|--|--|
| Code: YCL                       | 2.5 ft. | 10 - 2 |  |  |  |
| Observation: Crack Longitudinal |         |        |  |  |  |
| Remarks:                        |         |        |  |  |  |



|  |          |  |  |  |  |
|--|----------|--|--|--|--|
| Code: TIED                                   | 64.0 ft. |  |  |  |  |
| Observation: nspection Ends at Downstream MH |          |  |  |  |  |
| Remarks:                                     |          |  |  |  |  |

N120-36




### Scaled Plot

505-341-0109

|                                      |                               |              |          |              |                           |
|--------------------------------------|-------------------------------|--------------|----------|--------------|---------------------------|
| Pipe ID<br><b>N120-191</b>           | City                          | Street       | Shape    | Map #1       | Basin                     |
| <b>US Manhole</b><br><b>N120-191</b> | Section Length                | Year Laid    | Material | Section Type |                           |
| <b>DS Manhole</b><br><b>N120-36</b>  | Inspected Length<br><b>64</b> | Year Renewed | Depth US | Depth DS     | Joint Leng...<br>Diameter |

|                            |             |                      |                                      |        |  |
|----------------------------|-------------|----------------------|--------------------------------------|--------|--|
| Cleared                    |             | Situation            |                                      | Reason |  |
| Date<br><b>20181022</b>    | Clean Date  | Weather              |                                      | Remark |  |
| Start Time<br><b>10:55</b> |             |                      |                                      |        |  |
| Operator<br><b>CODY</b>    | Customer    | Truck<br><b>4161</b> | Inspection Dir.<br><b>Downstream</b> | Info   |  |
| Operator Comment           | P.O. Number | Present              | Flow Control                         | Camera |  |



\* = clock positions adjusted automatically for reverse inspection