




Left Plot w/ Pics

505-341-0109

Pipe ID N120-133	City	Street WREN RD 4850 S	Shape	Map #1	Basin
US Manhole N120-133	Section Length 51.55	Year Laid	Material	Section Type	
DS Manhole N120-184	Inspected Length 203.3	Year Renewed	Depth US N/A	Depth DS	Joint Leng... Diameter 8
Cleaned		Situation		Reason	
Date 20181019	Clean Date	Weather		Remark	
Start Time 09:40					
Operator CODY	Customer	Truck 4161	Inspection Dir. Upstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-184

Distance: Pos: Val 1 / 2 : % : Gallons:

	Code: TIBD	0.0 ft.					
Observation: Inspection Begins at Downstream MH							
Remarks:							
	Code: YBP	5.0 ft.	1				
Observation: Broken Broken Pipe							
Remarks:							
	Code: YHV	18.5 ft.	10 - 1				
Observation: Hole in pipe Void							
Remarks: LARGE VOID WITH GAS LIN THROUGH IT							
	Code: YHV	29.6 ft.	11 - 1				
Observation: Hole in pipe Void							
Remarks:							
	Code: CLV	73.3 ft.	9				
Observation: Lateral Active							
Remarks:							
	Code: CLV	131.8 ft.	9				
Observation: Lateral Active							
Remarks:							
	Code: CLV	195.4 ft.	9				
Observation: Lateral Active							
Remarks:							



Left Plot w/ Pics

505-341-0109

Pipe ID N120-133	City	Street WREN RD 4850 S	Shape	Map #1	Basin
US Manhole N120-133	Section Length 51.55	Year Laid	Material	Section Type	
DS Manhole N120-184	Inspected Length 203.3	Year Renewed	Depth US N/A	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20181019	Clean Date	Weather		Remark	
Start Time 09:40					
Operator CODY	Customer	Truck 4161	Inspection Dir. Upstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



Code: TGO 203.0 ft. 11 - 1

Observation: General Observation
Remarks: PAN OR SOMTHING IN MH



Code: TIEU 203.3 ft.

Observation: Inspection Ends at Upstream MH
Remarks:

N120-133




Scaled Plot

505-341-0109

Pipe ID N120-133	City	Street WREN RD 4850 S	Shape	Map #1	Basin
US Manhole N120-133	Section Length 51.55	Year Laid	Material	Section Type	
DS Manhole N120-184	Inspected Length 203.3	Year Renewed	Depth US N/A	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20181019	Clean Date	Weather		Remark	
Start Time 09:40					
Operator CODY	Customer	Truck 4161	Inspection Dir. Upstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:150