




### Left Plot w/ Pics

505-341-0109

Pipe ID <b>N120-184</b>	City	Street <b>WREN RD 4850 S</b>	Shape	Map #1	Basin
<b>US Manhole</b> N120-184	Section Length <b>60.487</b>	Year Laid	Material <b>CON</b>	Section Type	
<b>DS Manhole</b> N120-183	Inspected Length <b>186.2</b>	Year Renewed	Depth US <b>9</b>	Depth DS	Joint Leng... Diameter <b>8</b>
Cleaned		Situation		Reason	
Date <b>20181019</b>	Clean Date	Weather		Remark	
Start Time <b>11:04</b>					
Operator <b>CODY</b>	Customer	Truck <b>4161</b>	Inspection Dir. <b>Downstream</b>	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-184

Distance: Pos: Val 1 / 2 : % : Gallons:



Code: TIBU 0.0 ft.

Observation: Inspection Begins at Upstream MH

Remarks:



Code: YH 86.5 ft. 11 - 12

Observation: Hole in pipe

Remarks: SPAWL



Code: CLV 93.4 ft. 9

Observation: Lateral Active

Remarks:



Code: TIED 186.2 ft.

Observation: nspection Ends at Downstream MH

Remarks:

N120-183




### Scaled Plot

505-341-0109

Pipe ID <b>N120-184</b>	City	Street <b>WREN RD 4850 S</b>	Shape	Map #1	Basin
<b>US Manhole</b> <b>N120-184</b>	Section Length <b>60.487</b>	Year Laid	Material <b>CON</b>	Section Type	
<b>DS Manhole</b> <b>N120-183</b>	Inspected Length <b>186.2</b>	Year Renewed	Depth US <b>9</b>	Depth DS	Joint Leng... Diameter <b>8</b>

Cleared		Situation		Reason	
Date <b>20181019</b>	Clean Date	Weather		Remark	
Start Time <b>11:04</b>					
Operator <b>CODY</b>	Customer	Truck <b>4161</b>	Inspection Dir. <b>Downstream</b>	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



\* = clock positions adjusted automatically for reverse inspection