




Left Plot w/ Pics








505-341-0109

Pipe ID N120-183	City	Street WREN RD 4850 S	Shape	Map #1	Basin
US Manhole N120-183	Section Length 68.377	Year Laid	Material CON	Section Type	
DS Manhole N120-180	Inspected Length 215.6	Year Renewed	Depth US 9	Depth DS	Joint Leng... Diameter 8
Cleaned		Situation		Reason	
Date 20181019	Clean Date	Weather		Remark	
Start Time 11:15					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-183

Distance: Pos: Val 1 / 2 : % : Gallons:

	Code: TIBU	0.0 ft.					
Observation: Inspection Begins at Upstream MH							
Remarks:							
	Code: CLV	6.5 ft.	3				
Observation: Lateral Active							
Remarks:							
	Code: YCL	7.7 ft.	4 - 6				
Observation: Crack Longitudinal							
Remarks:							
	Code: CLV	9.0 ft.	3				
Observation: Lateral Active							
Remarks: MESSED UP INSIDE							
	Code: CLV	53.7 ft.	3				
Observation: Lateral Active							
Remarks:							
	Code: CLC	57.1 ft.	3				
Observation: Lateral Capped							
Remarks:							
	Code: TIED	215.6 ft.					
Observation: nspection Ends at Downstream MH							
Remarks:							



Left Plot w/ Pics

505-341-0109

Pipe ID N120-183	City	Street WREN RD 4850 S	Shape	Map #1	Basin
US Manhole N120-183	Section Length 68.377	Year Laid	Material CON	Section Type	
DS Manhole N120-180	Inspected Length 215.6	Year Renewed	Depth US 9	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20181019	Clean Date	Weather		Remark	
Start Time 11:15					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-180




Scaled Plot

505-341-0109

Pipe ID N120-183	City	Street WREN RD 4850 S	Shape	Map #1	Basin
US Manhole N120-183	Section Length 68.377	Year Laid	Material CON	Section Type	
DS Manhole N120-180	Inspected Length 215.6	Year Renewed	Depth US 9	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20181019	Clean Date	Weather		Remark	
Start Time 11:15					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection