




Left Plot w/ Pics








505-341-0109

Pipe ID N120-18	City	Street BON AIR ST 4885 S	Shape	Map #1	Basin
US Manhole N120-18	Section Length 76.374	Year Laid	Material CON	Section Type	
DS Manhole N120-17	Inspected Length 229.7	Year Renewed	Depth US 5	Depth DS	Joint Leng... Diameter 8
Cleaned		Situation		Reason	
Date 20181102	Clean Date	Weather		Remark	
Start Time 12:13					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-18

Distance: Pos: Val 1 / 2 : % : Gallons:

	Code: TIBU	0.0 ft.					
Observation: Inspection Begins at Upstream MH							
Remarks:							
	Code: CLV	20.4 ft.	3				
Observation: Lateral Active							
Remarks:							
	Code: YHV	65.6 ft.	11 - 1				
Observation: Hole in pipe Void							
Remarks:							
	Code: CLC	70.3 ft.	3				
Observation: Lateral Capped							
Remarks:							
	Code: CLC	102.4 ft.	3				
Observation: Lateral Capped							
Remarks:							
	Code: CLV	103.6 ft.	3				
Observation: Lateral Active							
Remarks:							
	Code: YCL	169.2 ft.	3 - 4				
Observation: Crack Longitudinal							
Remarks:							



Left Plot w/ Pics

505-341-0109

Pipe ID N120-18	City	Street BON AIR ST 4885 S	Shape	Map #1	Basin
US Manhole N120-18	Section Length 76.374	Year Laid	Material CON	Section Type	
DS Manhole N120-17	Inspected Length 229.7	Year Renewed	Depth US 5	Depth DS	Joint Leng... Diameter 8
Cleaned		Situation		Reason	
Date 20181102	Clean Date	Weather		Remark	
Start Time 12:13					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



Code: CLV 172.0 ft. 3

Observation: Lateral Active

Remarks:



Code: CLV 193.6 ft. 9

Observation: Lateral Active

Remarks:



Code: TIED 229.7 ft.

Observation: nspection Ends at Downstream MH

Remarks:

N120-17




Scaled Plot

505-341-0109

Pipe ID N120-18	City	Street BON AIR ST 4885 S	Shape	Map #1	Basin
US Manhole N120-18	Section Length 76.374	Year Laid	Material CON	Section Type	
DS Manhole N120-17	Inspected Length 229.7	Year Renewed	Depth US 5	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20181102	Clean Date	Weather		Remark	
Start Time 12:13					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:200