




Left Plot w/ Pics

505-341-0109

Pipe ID N120-180	City	Street HOLLADAY BLVD 2530 ...	Shape	Map #1	Basin
US Manhole N120-180	Section Length 62.821	Year Laid	Material CON	Section Type	
DS Manhole N120-179	Inspected Length 219.7	Year Renewed	Depth US 10	Depth DS	Joint Leng... Diameter 8
Cleaned		Situation		Reason	
Date 20181015	Clean Date	Weather		Remark	
Start Time 13:46					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-180

Distance: Pos: Val 1 / 2 : % : Gallons:




Code: TIBU 0.0 ft. Observation: Inspection Begins at Upstream MH
Remarks:



Code: CLV 21.9 ft. 3 Observation: Lateral Active
Remarks:



Code: CLV 217.5 ft. 3 Observation: Lateral Active
Remarks:



Code: TIED 219.7 ft. Observation: nspection Ends at Downstream MH
Remarks: ENDS 6 FT SHORT

N120-179




Scaled Plot

505-341-0109

Pipe ID N120-180	City	Street HOLLADAY BLVD 2530 ...	Shape	Map #1	Basin
US Manhole N120-180	Section Length 62.821	Year Laid	Material CON	Section Type	
DS Manhole N120-179	Inspected Length 219.7	Year Renewed	Depth US 10	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20181015	Clean Date	Weather		Remark	
Start Time 13:46		Truck 4161	Inspection Dir. Downstream	Info	
Operator CODY	Customer	Present	Flow Control	Camera	
Operator Comment	P.O. Number				



* = clock positions adjusted automatically for reverse inspection

Scale: 1:500