




Left Plot w/ Pics

505-341-0109

Pipe ID N120-179	City	Street HOLLADAY BLVD 2400 ...	Shape	Map #1	Basin
US Manhole N120-179	Section Length 84.283	Year Laid	Material CON	Section Type	
DS Manhole N120-172	Inspected Length 268.3	Year Renewed	Depth US 10	Depth DS	Joint Leng... Diameter 8
Cleaned		Situation		Reason	
Date 20181025	Clean Date	Weather		Remark	
Start Time 10:55					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-179

Distance: Pos: Val 1 / 2 : % : Gallons:



Code: TIBU 0.0 ft.

Observation: Inspection Begins at Upstream MH

Remarks:



Code: CLV 81.0 ft. 9

Observation: Lateral Active

Remarks:



Code: TIED 268.3 ft.

Observation: nspection Ends at Downstream MH

Remarks:

N120-172




Scaled Plot

505-341-0109

Pipe ID N120-179	City	Street HOLLADAY BLVD 2400 ...	Shape	Map #1	Basin
US Manhole N120-179	Section Length 84.283	Year Laid	Material CON	Section Type	
DS Manhole N120-172	Inspected Length 268.3	Year Renewed	Depth US 10	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20181025	Clean Date	Weather		Remark	
Start Time 10:55					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:850