



Left Plot w/ Pics








505-341-0109

Pipe ID L8-10	City	Street LINCOLN CIR 4155 S	Shape	Map #1	Basin
US Manhole L8-10	Section Length 91.669	Year Laid	Material PRC	Section Type	
DS Manhole L8-2	Inspected Length 116	Year Renewed	Depth US 10.5	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20160426	Clean Date	Weather		Remark	
Start Time 14:06					
Operator MIKE	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



L8-10

Distance: Pos: Val 1 / 2 : % : Gallons:

	Code: TIBU	0.0 ft.					
Observation: Inspection Begins at Upstream MH							
Remarks:							
	Code: CLV	5.1 ft.	9				
Observation: Lateral Active							
Remarks:							
	Code: CLV	8.9 ft.	3				
Observation: Lateral Active							
Remarks:							
	Code: CLV	54.3 ft.	9				
Observation: Lateral Active							
Remarks:							
	Code: TPR	113.9 ft.	12 - 12				
Observation: Point Repair Point Repair							
Remarks:							
	Code: CLV	114.6 ft.	9				
Observation: Lateral Active							
Remarks:							
	Code: TIA	116.0 ft.					
Observation: Inspection Abandoned							
Remarks:							



Left Plot w/ Pics

505-341-0109

Pipe ID L8-10	City	Street LINCOLN CIR 4155 S	Shape		Map #1	Basin
US Manhole L8-10	Section Length 91.669	Year Laid	Material PRC		Section Type	
DS Manhole L8-2	Inspected Length 116	Year Renewed	Depth US 10.5	Depth DS	Joint Leng...	Diameter 8
Cleared		Situation		Reason		
Date 20160426	Clean Date	Weather		Remark		
Start Time 14:06						
Operator MIKE	Customer	Truck 4165	Inspection Dir. DOWNSTREAM		Info	
Operator Comment	P.O. Number	Present	Flow Control		Camera	






Scaled Plot

505-341-0109

Pipe ID L8-10	City	Street LINCOLN CIR 4155 S	Shape	Map #1	Basin
US Manhole L8-10	Section Length 91.669	Year Laid	Material PRC	Section Type	
DS Manhole L8-2	Inspected Length 116	Year Renewed	Depth US 10.5	Depth DS	Joint Leng... Diameter 8

Cleaned		Situation		Reason	
Date 20160426	Clean Date	Weather		Remark	
Start Time 14:06					
Operator MIKE	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:400