




Left Plot w/ Pics

505-341-0109

Pipe ID L8-1	City	Street LYNNE LN 2000 E	Shape	Map #1	Basin
US Manhole L8-1	Section Length 65.531	Year Laid	Material CON	Section Type	
DS Manhole L8	Inspected Length 116.2	Year Renewed	Depth US 9	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20160503	Clean Date	Weather		Remark	
Start Time 11:13					
Operator MIKE	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



L8-1

Distance: Pos: Val 1 / 2 : % : Gallons:


Code: TIBU	0.0 ft.				
Observation: Inspection Begins at Upstream MH					
Remarks:					



Code: CLV	68.2 ft.	3			
Observation: Lateral Active					
Remarks:					



Code: CLV	116.2 ft.	9			
Observation: Lateral Active					
Remarks:					



L8




Scaled Plot

505-341-0109

Pipe ID L8-1	City	Street LYNNE LN 2000 E	Shape	Map #1	Basin
US Manhole L8-1	Section Length 65.531	Year Laid	Material CON	Section Type	
DS Manhole L8	Inspected Length 116.2	Year Renewed	Depth US 9	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20160503	Clean Date	Weather		Remark	
Start Time 11:13					
Operator MIKE	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:650