



Left Plot w/ Pics

505-341-0109

| | | | | | |
|-------------------------------------|----------------------------------|---|--------------------------------------|--------------|---------------------------------------|
| Pipe ID N143-23 | City | Street HOLLADAY BLVD 2720 ... | Shape | Map #1 | Basin |
| US Manhole N143-23 | Section Length 73.423 | Year Laid | Material CON | Section Type | |
| DS Manhole N143-22 | Inspected Length 323.1 | Year Renewed | Depth US 8 | Depth DS | Joint Leng... Diameter 8 |
| Cleaned | Situation | | Reason | | |
| Date 20181109 | Clean Date | Weather | | Remark | |
| Start Time 13:33 | | | | | |
| Operator STEVEN | Customer | Truck 4165 | Inspection Dir. DOWNSTREAM | Info | |
| Operator Comment | P.O. Number | Present | Flow Control | Camera | |



N143-23

Distance: Pos: Val 1 / 2 : % : Gallons:




| | | | | | |
|---|---------|--|--|--|--|
| Code: TIBU | 0.0 ft. | | | | |
| Observation: Inspection Begins at Upstream MH | | | | | |
| Remarks: | | | | | |



| | | | | | |
|-------------------------------------|---------|-------|--|--|--|
| Code: YWC | 9.3 ft. | 8 - 4 | | | |
| Observation: Wall Surface Corrosion | | | | | |
| Remarks: H2S | | | | | |




| | | | | | |
|---------------------------------|----------|-------|--|--|--|
| Code: YCL | 19.0 ft. | 7 - 8 | | | |
| Observation: Crack Longitudinal | | | | | |
| Remarks: | | | | | |



| | | | | | |
|----------------------------------|----------|--|--|--|--|
| Code: TGO | 21.6 ft. | | | | |
| Observation: General Observation | | | | | |
| Remarks: LOW AREA | | | | | |



| | | | | | |
|---------------------------------|-----------|-------|--|--|--|
| Code: YCL | 103.3 ft. | 8 - 9 | | | |
| Observation: Crack Longitudinal | | | | | |
| Remarks: | | | | | |



| | | | | | |
|----------------------------------|-----------|--|--|--|--|
| Code: TGO | 119.9 ft. | | | | |
| Observation: General Observation | | | | | |
| Remarks: 4164 PULLING WATER | | | | | |



| | | | | | |
|----------------------------------|-----------|--|--|--|--|
| Code: TGO | 130.3 ft. | | | | |
| Observation: General Observation | | | | | |
| Remarks: LOW AREA | | | | | |




Left Plot w/ Pics

505-341-0109

| | | | | | |
|-------------------------------------|----------------------------------|---|--------------------------------------|--------------|---------------------------------------|
| Pipe ID N143-23 | City | Street HOLLADAY BLVD 2720 ... | Shape | Map #1 | Basin |
| US Manhole N143-23 | Section Length 73.423 | Year Laid | Material CON | Section Type | |
| DS Manhole N143-22 | Inspected Length 323.1 | Year Renewed | Depth US 8 | Depth DS | Joint Leng... Diameter 8 |
| Cleaned | Situation | | Reason | | |
| Date 20181109 | Clean Date | Weather | | Remark | |
| Start Time 13:33 | | | | | |
| Operator STEVEN | Customer | Truck 4165 | Inspection Dir. DOWNSTREAM | Info | |
| Operator Comment | P.O. Number | Present | Flow Control | Camera | |

| | | | | | |
|--|-----------|--|--|--|--|
| Code: TIED | 323.1 ft. | | | | |
| Observation: nspection Ends at Downstream MH | | | | | |
| Remarks: LOW AREAS / DETERIATION HVY. | | | | | |



N143-22




Scaled Plot

505-341-0109

| | | | | | |
|-------------------------------------|----------------------------------|---|------------------------|--------------|---------------------------------------|
| Pipe ID N143-23 | City | Street HOLLADAY BLVD 2720 ... | Shape | Map #1 | Basin |
| US Manhole N143-23 | Section Length 73.423 | Year Laid | Material CON | Section Type | |
| DS Manhole N143-22 | Inspected Length 323.1 | Year Renewed | Depth US 8 | Depth DS | Joint Leng... Diameter 8 |

| | | | | | |
|----------------------------|-------------|----------------------|--------------------------------------|--------|--|
| Cleaned | | Situation | | Reason | |
| Date 20181109 | Clean Date | Weather | | Remark | |
| Start Time 13:33 | | | | | |
| Operator STEVEN | Customer | Truck 4165 | Inspection Dir. DOWNSTREAM | Info | |
| Operator Comment | P.O. Number | Present | Flow Control | Camera | |



* = clock positions adjusted automatically for reverse inspection

Scale: 1:250