



Left Plot w/ Pics








505-341-0109

Pipe ID N143-22	City	Street 2720 E	Shape	Map #1	Basin
US Manhole N143-22	Section Length 90.435	Year Laid	Material CON	Section Type	
DS Manhole N143-9	Inspected Length 342.8	Year Renewed	Depth US 8	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20181109	Clean Date	Weather		Remark	
Start Time 14:30					
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N143-22

Distance: Pos: Val 1 / 2 : % : Gallons:

	Code: TIBU	0.0 ft.					
Observation: Inspection Begins at Upstream MH							
Remarks: 4162 PULLING WATER							
	Code: YWC	89.8 ft.	8 - 4				
Observation: Wall Surface Corrosion							
Remarks:							
	Code: TGO	123.6 ft.					
Observation: General Observation							
Remarks: LOW AREA							
	Code: TGO	182.7 ft.	11 - 12				
Observation: General Observation							
Remarks: CRACK							
	Code: CLC	216.3 ft.	9				
Observation: Lateral Capped							
Remarks:							
	Code: CLV	275.3 ft.	9				
Observation: Lateral Active							
Remarks:							
	Code: TIED	342.8 ft.					
Observation: nspection Ends at Downstream MH							
Remarks: 4162 CLEANED AND PULLED WATER / HVY DETERIATION							



Left Plot w/ Pics

505-341-0109

Pipe ID N143-22	City	Street 2720 E	Shape		Map #1	Basin
US Manhole N143-22	Section Length 90.435	Year Laid	Material CON		Section Type	
DS Manhole N143-9	Inspected Length 342.8	Year Renewed	Depth US 8	Depth DS	Joint Leng...	Diameter 8
Cleared		Situation		Reason		
Date 20181109	Clean Date	Weather		Remark		
Start Time 14:30						
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM		Info	
Operator Comment	P.O. Number	Present	Flow Control		Camera	



N143-9




Scaled Plot

505-341-0109

Pipe ID N143-22	City	Street 2720 E	Shape	Map #1	Basin
US Manhole N143-22	Section Length 90.435	Year Laid	Material CON	Section Type	
DS Manhole N143-9	Inspected Length 342.8	Year Renewed	Depth US 8	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20181109	Clean Date	Weather		Remark	
Start Time 14:30					
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:400