



### Left Plot w/ Pics








505-341-0109

|                                   |                                  |   |                                      |              |  |
|-----------------------------------|----------------------------------|---|--------------------------------------|--------------|--|
| Pipe ID<br><b>L12-2</b>           | City                             | Street<br><b>CUMBERLAND RD 2145 ...</b> | Shape                                | Map #1       | Basin                                  |
| <b>US Manhole</b><br><b>L12-2</b> | Section Length<br><b>80.698</b>  | Year Laid                               | Material<br><b>CON</b>               | Section Type |  |
| <b>DS Manhole</b><br><b>L12-1</b> | Inspected Length<br><b>214.9</b> | Year Renewed                            | Depth US<br><b>12</b>                | Depth DS     | Joint Leng...<br>Diameter<br><b>10</b> |
| Cleaned                           | Situation                        |   | Reason                               |              |  |
| Date<br><b>20170302</b>           | Clean Date                       | Weather                                 |                                      | Remark       |  |
| Start Time<br><b>13:40</b>        |                                  |   |                                      |              |  |
| Operator<br><b>STEVEN</b>         | Customer                         | Truck<br><b>4165</b>                    | Inspection Dir.<br><b>DOWNSTREAM</b> | Info         |  |
| Operator Comment                  | P.O. Number                      | Present                                 | Flow Control                         | Camera       |  |



L12-2

Distance: Pos: Val 1 / 2 : % : Gallons:

|   |            |           |         |  |  |  |  |
|---|------------|-----------|---------|--|--|--|--|
|    | Code: TIBU | 0.0 ft.   |         |  |  |  |  |
| Observation: Inspection Begins at Upstream MH                                       |            |           |         |  |  |  |  |
| Remarks:  |            |           |         |  |  |  |  |
|   | Code: YJOM | 3.2 ft.   |         |  |  |  |  |
| Observation: Joint Offset Medium  |            |           |         |  |  |  |  |
| Remarks:  |            |           |         |  |  |  |  |
|  | Code: CLV  | 52.9 ft.  | 3       |  |  |  |  |
| Observation: Lateral Active   |            |           |         |  |  |  |  |
| Remarks:  |            |           |         |  |  |  |  |
|  | Code: TGO  | 59.8 ft.  |         |  |  |  |  |
| Observation: General Observation  |            |           |         |  |  |  |  |
| Remarks: STICK  |            |           |         |  |  |  |  |
|  | Code: CLV  | 126.1 ft. | 3       |  |  |  |  |
| Observation: Lateral Active   |            |           |         |  |  |  |  |
| Remarks:  |            |           |         |  |  |  |  |
|  | Code: YCL  | 151.2 ft. | 5 - 6   |  |  |  |  |
| Observation: Crack Longitudinal   |            |           |         |  |  |  |  |
| Remarks: IN FLOOR / FLOW LINE   |            |           |         |  |  |  |  |
|  | Code: YCC  | 207.9 ft. | 12 - 12 |  |  |  |  |
| Observation: Crack Circumferential  |            |           |         |  |  |  |  |
| Remarks:  |            |           |         |  |  |  |  |



### Left Plot w/ Pics

505-341-0109

|                                   |                                  |   |                                      |              |  |
|-----------------------------------|----------------------------------|---|--------------------------------------|--------------|--|
| Pipe ID<br><b>L12-2</b>           | City                             | Street<br><b>CUMBERLAND RD 2145 ...</b> | Shape                                | Map #1       | Basin                                  |
| <b>US Manhole</b><br><b>L12-2</b> | Section Length<br><b>80.698</b>  | Year Laid                               | Material<br><b>CON</b>               | Section Type |  |
| <b>DS Manhole</b><br><b>L12-1</b> | Inspected Length<br><b>214.9</b> | Year Renewed                            | Depth US<br><b>12</b>                | Depth DS     | Joint Leng...<br>Diameter<br><b>10</b> |
| Cleaned                           | Situation                        |   | Reason                               |              |  |
| Date<br><b>20170302</b>           | Clean Date                       | Weather                                 |                                      | Remark       |  |
| Start Time<br><b>13:40</b>        |                                  |   |                                      |              |  |
| Operator<br><b>STEVEN</b>         | Customer                         | Truck<br><b>4165</b>                    | Inspection Dir.<br><b>DOWNSTREAM</b> | Info         |  |
| Operator Comment                  | P.O. Number                      | Present                                 | Flow Control                         | Camera       |  |



Code: YCC      210.8 ft.      12 - 12

Observation: Crack Circumferential

Remarks:



Code: TIED      214.9 ft.

Observation: nspection Ends at Downstream MH

Remarks: HVY DETERIATION / CRACKS / HAD 4168 PULL STICK OUT

L12-1




### Scaled Plot

505-341-0109

|                                   |                                  |   |                        |              |  |
|-----------------------------------|----------------------------------|---|------------------------|--------------|--|
| Pipe ID<br><b>L12-2</b>           | City                             | Street<br><b>CUMBERLAND RD 2145 ...</b> | Shape                  | Map #1       | Basin                                  |
| <b>US Manhole</b><br><b>L12-2</b> | Section Length<br><b>80.698</b>  | Year Laid                               | Material<br><b>CON</b> | Section Type |  |
| <b>DS Manhole</b><br><b>L12-1</b> | Inspected Length<br><b>214.9</b> | Year Renewed                            | Depth US<br><b>12</b>  | Depth DS     | Joint Leng...<br>Diameter<br><b>10</b> |

|                            |             |                      |                                      |        |  |
|----------------------------|-------------|----------------------|--------------------------------------|--------|--|
| Cleansed                   |             | Situation            |                                      | Reason |  |
| Date<br><b>20170302</b>    | Clean Date  | Weather              |                                      | Remark |  |
| Start Time<br><b>13:40</b> |             |                      |                                      |        |  |
| Operator<br><b>STEVEN</b>  | Customer    | Truck<br><b>4165</b> | Inspection Dir.<br><b>DOWNSTREAM</b> | Info   |  |
| Operator Comment           | P.O. Number | Present              | Flow Control                         | Camera |  |



\* = clock positions adjusted automatically for reverse inspection

Scale: 1:250