



Left Plot w/ Pics

505-341-0109

Pipe ID L12-3	City	Street CUMBERLAND RD 2145 ...	Shape	Map #1	Basin
US Manhole L12-3	Section Length 65.804	Year Laid	Material CON	Section Type	
DS Manhole L12-2	Inspected Length 251.7	Year Renewed	Depth US 13	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20170302	Clean Date	Weather		Remark	
Start Time 13:18					
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	




L12-3


Distance: Pos: Val 1 / 2 : % : Gallons:



Code: TIBU	0.0 ft.				
Observation: Inspection Begins at Upstream MH					
Remarks:					



Code: CLV	4.0 ft.	3			
Observation: Lateral Active					
Remarks:					




Code: YCL	10.4 ft.	12 - 1			
Observation: Crack Longitudinal					
Remarks:					




Code: CLV	119.9 ft.	9			
Observation: Lateral Active					
Remarks:					



Code: CLV	121.5 ft.	9			
Observation: Lateral Active					
Remarks:					



Code: CLV	148.5 ft.	3			
Observation: Lateral Active					
Remarks:					



Code: TPR	203.1 ft.	12 - 12			
Observation: Point Repair Point Repair					
Remarks: C-900					




Left Plot w/ Pics

505-341-0109

Pipe ID L12-3	City	Street CUMBERLAND RD 2145 ...	Shape	Map #1	Basin
US Manhole L12-3	Section Length 65.804	Year Laid	Material CON	Section Type	
DS Manhole L12-2	Inspected Length 251.7	Year Renewed	Depth US 13	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20170302	Clean Date	Weather		Remark	
Start Time 13:18					
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



Code: CLV	204.1 ft.	9			
Observation: Lateral Active					
Remarks:					



Code: CLV	205.3 ft.	9			
Observation: Lateral Active					
Remarks:					



Code: YCC	239.3 ft.	12 - 12			
Observation: Crack Circumferential					
Remarks:					



Code: YCC	245.4 ft.	12 - 12			
Observation: Crack Circumferential					
Remarks:					



Code: YCC	246.4 ft.	12 - 12			
Observation: Crack Circumferential					
Remarks:					



Code: TIED	251.7 ft.				
Observation: nspection Ends at Downstream MH					
Remarks: MED TO HVY DETERIATION / CRACKS					



L12-2




Scaled Plot

505-341-0109

Pipe ID L12-3	City	Street CUMBERLAND RD 2145 ...	Shape	Map #1	Basin
US Manhole L12-3	Section Length 65.804	Year Laid	Material CON	Section Type	
DS Manhole L12-2	Inspected Length 251.7	Year Renewed	Depth US 13	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20170302	Clean Date	Weather		Remark	
Start Time 13:18					
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:150