




Left Plot w/ Pics


505-341-0109

Pipe ID N120-96	City	Street NANILOA DR 2870 E	Shape	Map #1	Basin
US Manhole N120-96	Section Length 38.14	Year Laid	Material PRC	Section Type	
DS Manhole N120-90	Inspected Length 83.3	Year Renewed	Depth US 10	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20170816	Clean Date	Weather		Remark	
Start Time 08:48					
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	




N120-96

Distance: Pos: Val 1 / 2 : % : Gallons:




Code: TIBU	0.0 ft.				
Observation: Inspection Begins at Upstream MH					
Remarks:					



Code: TGO	0.0 ft.				
Observation: General Observation					
Remarks: INSPECT SERVICE LINER					



Code: CLV	58.5 ft.	9			
Observation: Lateral Active					
Remarks: SERVICE WITH LINER					



Code: TGO	59.6 ft.				
Observation: General Observation					
Remarks: LINER LOOKS GOOD					



Code: TIED	83.3 ft.				
Observation: Inspection Ends at Downstream MH					
Remarks: LINER IN SERVICE LOOKS GOOD					

N120-90




Scaled Plot

505-341-0109

Pipe ID N120-96	City	Street NANILOA DR 2870 E	Shape	Map #1	Basin
US Manhole N120-96	Section Length 38.14	Year Laid	Material PRC	Section Type	
DS Manhole N120-90	Inspected Length 83.3	Year Renewed	Depth US 10	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20170816	Clean Date	Weather		Remark	
Start Time 08:48					
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:500