



Left Plot w/ Pics

505-341-0109

Pipe ID E12-1	City	Street 1100 E	Shape	Map #1	Basin
US Manhole E12-1	Section Length 105.5	Year Laid	Material CON	Section Type	
DS Manhole E12	Inspected Length 310.1	Year Renewed	Depth US 10	Depth DS	Joint Leng... Diameter 10
Cleaned	Situation		Reason		
Date 20170831	Clean Date	Weather		Remark	
Start Time 11:00					
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	




E12-1

Distance: Pos: Val 1 / 2 : % : Gallons:




Code: TIBU	0.0 ft.				
Observation: Inspection Begins at Upstream MH					
Remarks:					



Code: TGO	0.0 ft.				
Observation: General Observation					
Remarks: INSPECT SERVICE LINER AT 4101 S					



Code: MIR	31.1 ft.	9 - 1			
Observation: Infiltration Running					
Remarks:					




Code: CLV	47.6 ft.	3			
Observation: Lateral Active					
Remarks:					



Code: CLV	86.9 ft.	9			
Observation: Lateral Active					
Remarks:					



Code: CLV	99.7 ft.	9			
Observation: Lateral Active					
Remarks:					



Code: YCL	105.1 ft.	12 - 1			
Observation: Crack Longitudinal					
Remarks:					




Left Plot w/ Pics

505-341-0109

Pipe ID E12-1	City	Street 1100 E	Shape	Map #1	Basin
US Manhole E12-1	Section Length 105.5	Year Laid	Material CON	Section Type	
DS Manhole E12	Inspected Length 310.1	Year Renewed	Depth US 10	Depth DS	Joint Leng... Diameter 10
Cleaned	Situation		Reason		
Date 20170831	Clean Date	Weather		Remark	
Start Time 11:00					
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	




Code: MID	107.8 ft.	11 - 1			
Observation: Infiltration Dripping					
Remarks:					




Code: MIR	120.0 ft.	2 - 3			
Observation: Infiltration Running					
Remarks:					




Code: MIG	123.4 ft.	9 - 12			
Observation: Infiltration Gushing					
Remarks:					



Code: YCL	124.6 ft.	11 - 12			
Observation: Crack Longitudinal					
Remarks:					




Code: CLV	134.8 ft.	3			
Observation: Lateral Active					
Remarks:					



Code: MIG	138.4 ft.	10 - 2			
Observation: Infiltration Gushing					
Remarks:					



Code: CLC	206.1 ft.	3			
Observation: Lateral Capped					
Remarks:					




Code: CLV	294.9 ft.	9			
Observation: Lateral Active					
Remarks:					



Left Plot w/ Pics

505-341-0109


Pipe ID E12-1	City	Street 1100 E	Shape	Map #1	Basin
US Manhole E12-1	Section Length 105.5	Year Laid	Material CON	Section Type	
DS Manhole E12	Inspected Length 310.1	Year Renewed	Depth US 10	Depth DS	Joint Leng... Diameter 10
Cleaned	Situation		Reason		
Date 20170831	Clean Date	Weather		Remark	
Start Time 11:00					
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



Code: TGO 310.1 ft.

Observation: General Observation

Remarks: SERVICE LINER LOOKED GOOD / CRACKS / I/I



Code: TIED 310.1 ft.

Observation: nspection Ends at Downstream MH

Remarks: ENDS AT DROP

E12




Scaled Plot

505-341-0109

Pipe ID E12-1	City	Street 1100 E	Shape	Map #1	Basin
US Manhole E12-1	Section Length 105.5	Year Laid	Material CON	Section Type	
DS Manhole E12	Inspected Length 310.1	Year Renewed	Depth US 10	Depth DS	Joint Leng... Diameter 10

Cleared		Situation		Reason	
Date 20170831	Clean Date	Weather		Remark	
Start Time 11:00					
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:550




Scaled Plot

505-341-0109

Pipe ID E12-1	City	Street 1100 E	Shape	Map #1	Basin
US Manhole E12-1	Section Length 105.5	Year Laid	Material CON	Section Type	
DS Manhole E12	Inspected Length 310.1	Year Renewed	Depth US 10	Depth DS	Joint Leng... Diameter 10

Cleared		Situation		Reason	
Date 20170831	Clean Date	Weather		Remark	
Start Time 11:00					
Operator STEVEN	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:550