




Left Plot w/ Pics


505-341-0109

Pipe ID N120-90	City	Street NANILOA DR 2870 E	Shape	Map #1	Basin
US Manhole N120-90	Section Length 57.007	Year Laid	Material PRC	Section Type	
DS Manhole N120-89	Inspected Length 172.7	Year Renewed	Depth US 11	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20181003	Clean Date	Weather		Remark	
Start Time 11:37					
Operator MIKE	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-90

Distance: Pos: Val 1 / 2 : % : Gallons:



Code: TIBU 0.0 ft.

Observation: Inspection Begins at Upstream MH

Remarks:



Code: CLV 80.2 ft. 3

Observation: Lateral Active

Remarks:



Code: CLV 136.1 ft. 9

Observation: Lateral Active

Remarks:



Code: TGO 163.0 ft.

Observation: General Observation

Remarks: SPALL??



Code: TIED 172.7 ft.

Observation: nspection Ends at Downstream MH

Remarks: DROP

N120-89




Scaled Plot

505-341-0109

Pipe ID N120-90	City	Street NANILOA DR 2870 E	Shape	Map #1	Basin
US Manhole N120-90	Section Length 57.007	Year Laid	Material PRC	Section Type	
DS Manhole N120-89	Inspected Length 172.7	Year Renewed	Depth US 11	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20181003	Clean Date	Weather		Remark	
Start Time 11:37					
Operator MIKE	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection