



Left Plot w/ Pics








505-341-0109

Pipe ID D49-69	City	Street STRATTON DR 3075 E	Shape	Map #1	Basin
US Manhole D49-69	Section Length 45.014	Year Laid	Material PRC	Section Type	
DS Manhole D49-68	Inspected Length 177.3	Year Renewed	Depth US 8.9	Depth DS	Joint Leng... Diameter 12
Cleaned	Situation		Reason		
Date 20181226	Clean Date	Weather		Remark	
Start Time 13:27					
Operator KEVINT	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



D49-69

Distance: Pos: Val 1 / 2 : % : Gallons:

	Code: TIBU	0.0 ft.						
Observation: Inspection Begins at Upstream MH								
Remarks:								
	Code: CLV	68.1 ft.	3					
Observation: Lateral Active								
Remarks:								
	Code: CLV	71.2 ft.	3					
Observation: Lateral Active								
Remarks:								
	Code: MRM	92.8 ft.	3 - 6					
Observation: Roots medium								
Remarks:								
	Code: MRM	106.7 ft.	6 - 11					
Observation: Roots medium								
Remarks:								
	Code: MRS	117.7 ft.	2 - 10					
Observation: Roots slight								
Remarks:								
	Code: TIED	177.3 ft.						
Observation: nspection Ends at Downstream MH								
Remarks: ROOTS								



Left Plot w/ Pics

505-341-0109

Pipe ID D49-69	City	Street STRATTON DR 3075 E	Shape		Map #1	Basin
US Manhole D49-69	Section Length 45.014	Year Laid	Material PRC		Section Type	
DS Manhole D49-68	Inspected Length 177.3	Year Renewed	Depth US 8.9	Depth DS	Joint Leng...	Diameter 12
Cleansed		Situation		Reason		
Date 20181226	Clean Date	Weather		Remark		
Start Time 13:27						
Operator KEVINT	Customer	Truck 4165	Inspection Dir. DOWNSTREAM		Info	
Operator Comment	P.O. Number	Present	Flow Control		Camera	



D49-68




Scaled Plot

505-341-0109

Pipe ID D49-69	City	Street STRATTON DR 3075 E	Shape	Map #1	Basin
US Manhole D49-69	Section Length 45.014	Year Laid	Material PRC	Section Type	
DS Manhole D49-68	Inspected Length 177.3	Year Renewed	Depth US 8.9	Depth DS	Joint Leng... Diameter 12

Cleared		Situation		Reason	
Date 20181226	Clean Date	Weather		Remark	
Start Time 13:27					
Operator KEVINT	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:200