




Left Plot w/ Pics

505-341-0109

Pipe ID D49-68	City	Street 3085 E	Shape	Map #1	Basin
US Manhole D49-68	Section Length 36.75	Year Laid	Material	Section Type	
DS Manhole D49-67	Inspected Length 95	Year Renewed	Depth US N/A	Depth DS	Joint Leng... Diameter 12
Cleaned		Situation		Reason	
Date 20160823	Clean Date	Weather		Remark	
Start Time 14:03					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



D49-68

Distance: Pos: Val 1 / 2 : % : Gallons:



Code: TIBU	0.0 ft.				
Observation: Inspection Begins at Upstream MH					
Remarks:					



Code: CLV	59.6 ft.	9			
Observation: Lateral Active					
Remarks:					



Code: TIED	95.0 ft.				
Observation: nspection Ends at Downstream MH					
Remarks:					

D49-67




Scaled Plot

505-341-0109

Pipe ID D49-68	City	Street 3085 E	Shape	Map #1	Basin
US Manhole D49-68	Section Length 36.75	Year Laid	Material	Section Type	
DS Manhole D49-67	Inspected Length 95	Year Renewed	Depth US N/A	Depth DS	Joint Leng... Diameter 12

Cleared		Situation		Reason	
Date 20160823	Clean Date	Weather		Remark	
Start Time 14:03					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:1000