




Left Plot w/ Pics

505-341-0109


Pipe ID F12	City	Street	Shape	Map #1	Basin
US Manhole	Section Length 81.102	Year Laid	Material	Section Type	
DS Manhole	Inspected Length 264.1	Year Renewed	Depth US N/A	Depth DS	Joint Leng... Diameter 18
Cleaned	Situation		Reason		
Date 20181012	Clean Date	Weather		Remark	
Start Time 14:17					
Operator KEVINT	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	




F12

Distance: Pos: Val 1 / 2 : % : Gallons:


Code: TIBU	0.0 ft.					
Observation: Inspection Begins at Upstream MH						
Remarks:						



Code: CLC	235.4 ft.	3				
Observation: Lateral Capped						
Remarks:						



Code: CLV	255.4 ft.	9				
Observation: Lateral Active						
Remarks:						



Code: TIED	264.1 ft.					
Observation: nspection Ends at Downstream MH						
Remarks:						



F11




Scaled Plot

505-341-0109

Pipe ID F12	City	Street	Shape	Map #1	Basin
US Manhole F12	Section Length 81.102	Year Laid	Material	Section Type	
DS Manhole F11	Inspected Length 264.1	Year Renewed	Depth US N/A	Depth DS	Joint Leng... Diameter 18

Cleared		Situation		Reason	
Date 20181012	Clean Date	Weather		Remark	
Start Time 14:17					
Operator KEVINT	Customer	Truck 4165	Inspection Dir. DOWNSTREAM	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:600