




Left Plot w/ Pics

505-341-0109

Pipe ID N120-87	City	Street WANDER CIR 4800 S	Shape	Map #1	Basin
US Manhole N120-87	Section Length 57.819	Year Laid	Material PRC	Section Type	
DS Manhole N120-83	Inspected Length 204.8	Year Renewed	Depth US 6	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20181009	Clean Date	Weather		Remark	
Start Time 11:17					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-87

Distance: Pos: Val 1 / 2 : % : Gallons:



Code: TIBU 0.0 ft.

Observation: Inspection Begins at Upstream MH

Remarks:



Code: CLV 103.6 ft. 3

Observation: Lateral Active

Remarks:



Code: TIED 204.8 ft.

Observation: nspection Ends at Downstream MH

Remarks:

N120-83




Scaled Plot

505-341-0109

Pipe ID N120-87	City	Street WANDER CIR 4800 S	Shape	Map #1	Basin
US Manhole N120-87	Section Length 57.819	Year Laid	Material PRC	Section Type	
DS Manhole N120-83	Inspected Length 204.8	Year Renewed	Depth US 6	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20181009	Clean Date	Weather		Remark	
Start Time 11:17					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection