



Left Plot w/ Pics








505-341-0109

Pipe ID N120-80	City	Street WANDER LN 2780 E	Shape	Map #1	Basin
US Manhole N120-80	Section Length 123.655	Year Laid	Material PRC	Section Type	
DS Manhole N120-48	Inspected Length 367.1	Year Renewed	Depth US 7	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20181010	Clean Date	Weather		Remark	
Start Time 13:08					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-80

Distance: Pos: Val 1 / 2 : % : Gallons:

	Code: TIBU	0.0 ft.					
Observation: Inspection Begins at Upstream MH							
Remarks:							
	Code: CLV	51.9 ft.	3				
Observation: Lateral Active							
Remarks:							
	Code: CLV	59.9 ft.	3				
Observation: Lateral Active							
Remarks:							
	Code: CLV	139.8 ft.	3				
Observation: Lateral Active							
Remarks:							
	Code: CLV	243.5 ft.	3				
Observation: Lateral Active							
Remarks:							
	Code: CLV	264.0 ft.	3				
Observation: Lateral Active							
Remarks:							
	Code: CLV	334.9 ft.	9				
Observation: Lateral Active							
Remarks:							



Left Plot w/ Pics

505-341-0109


Pipe ID N120-80	City	Street WANDER LN 2780 E	Shape	Map #1	Basin
US Manhole N120-80	Section Length 123.655	Year Laid	Material PRC	Section Type	
DS Manhole N120-48	Inspected Length 367.1	Year Renewed	Depth US 7	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20181010	Clean Date	Weather		Remark	
Start Time 13:08	Operator CODY		Customer	Truck 4161	Inspection Dir. Downstream
Operator Comment	P.O. Number	Present	Flow Control	Info	Camera



Code: TIED 367.1 ft.

Observation: nspection Ends at Downstream MH

Remarks:



N120-48




Scaled Plot

505-341-0109

Pipe ID N120-80	City	Street WANDER LN 2780 E	Shape	Map #1	Basin
US Manhole N120-80	Section Length 123.655	Year Laid	Material PRC	Section Type	
DS Manhole N120-48	Inspected Length 367.1	Year Renewed	Depth US 7	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20181010	Clean Date	Weather		Remark	
Start Time 13:08					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:1200