



N82-90 TV Observations

Footage	Digital Time	Clock From	Clock To	Code	Observation	Remarks
0	4			AMH	Manhole	OK
0	7			MWL	Water Level	
10.5	32	3		TF	Tap Factory	
30.2	71	9		TF	Tap Factory	
61.9	176	3	9	FM	Fracture Multiple	
90.4	247	9		TB	Tap Break-in	
98	273	3		TF	Tap Factory	
144.0	362	5	7	DFI	Dist. Fract. Int.	



N82-90 TV Observations

90.4	247	9		TB	Tap Break-in	
98	273	3		TF	Tap Factory	
144.9	363	5	7	RFJ	Roots Fine Joint	
173.3	415	9		TF	Tap Factory	
177.3	439	3		TF	Tap Factory	
180.6	455	3	5	RFJ	Roots Fine Joint	
181.4	485	3		TF	Tap Factory	ROOTS IN SERVICE
296	705			AMH	Manhole	ROOT, OLD FRACTURE