



C46-95 TV Observations

Footage	Digital Time	Clock From	Clock To	Code	Observation	Remarks
0	5			AMH	Manhole	OK
0	7			MWL	Water Level	
9.1	58	3		TB	Tap Break-in	ROOTS FROM SERVICE
99.5	176	7	8	RFJ	Roots Fine Joint	
120.3	208	9		TF	Tap Factory	
136.6	238	3		TF	Tap Factory	
213.1	358			AMH	Manhole	SLIGHT ROOT'S