



### C46-94 TV Observations

Footage	Digital Time	Clock From	Clock To	Code	Observation	Remarks
0	5			AMH	Manhole	OK
0	8			MWL	Water Level	
14.8	43	3		TF	Tap Factory	
26.8	68	9		TF	Tap Factory	
28.6	78	9		TB	Tap Break-in	
33.1	114	12	12	CC	Crack Circumferential	WITH ROOT'S
95	205	9		TF	Tap Factory	
139	270	7	8	RFI	Roots Fine Joint	



#### C46-94 TV Observations

139	270	7	8	RFJ	Roots Fine Joint	
139.3	279	3		TF	Tap Factory	
140.8	307	3		TB	Tap Break-in	ROOT'S FROM SERVICE
143.3	319	3		TF	Tap Factory	
151.2	342	4	8	RFJ	Roots Fine Joint	
170.6	390	8	4	SAVC	Surface Aggregate Visible Chemical	
198.3	434	3		TB	Tap Break-in	
241.3	573			AMH	Manhole	LITE ROOT'S AND DETERIATION