






**I97 TV Observations Dec 07 2018**

Footage	Digital Time	Clock From	Clock To	Code	Observation Type	Observation	Remarks	Observation Image
0.00	11.678			TIBD		Inspection Begins at Downstream MH		
41.00	230.064	9	3	TGO		General Observation	H2S	
57.20	298.833	9	3	TGO		General Observation	H2S	



**I97 TV Observations Dec 07 2018**

87.80	426.395	9	3	TGO		General Observation	H2S	
102.00	551.053	3	9	MDG	O&M	Debris Gravel		
104.90	628.163	9	3	TGO		General Observation	H2S	



**I97 TV Observations Dec 07 2018**

102.00	551.053	3	9	MDG	O&M	Debris Gravel		
104.90	628.163	9	3	TGO		General Observation	H2S	
117.10	832.535			TIEU		Inspection Ends at Upstream MH		