




Left Plot w/ Pics

505-341-0109


| | | | | | |
|---------------------------------|---------------------------------|-------------------------------------|------------------------------------|--------------|--|
| Pipe ID F14 | City | Street MURRAY HOLLADAY RD | Shape | Map #1 | Basin |
| US Manhole F14 | Section Length 20.951 | Year Laid | Material | Section Type | |
| DS Manhole F13 | Inspected Length 65.3 | Year Renewed | Depth US N/A | Depth DS | Joint Leng... Diameter 18 |
| Cleaned | Situation | | Reason | | |
| Date 20181012 | Clean Date | Weather | | Remark | |
| Start Time 14:01 | | | | | |
| Operator KEVINT | Customer | Truck 4165 | Inspection Dir. UPSTREAM | Info | |
| Operator Comment | P.O. Number | Present | Flow Control | Camera | |




F13

Distance: Pos: Val 1 / 2 : % : Gallons:


| | | | | | |
|---|---------|--|--|--|--|
| Code: TIBD | 0.0 ft. | | | | |
| Observation: Inspection Begins at Downstream MH | | | | | |
| Remarks: | | | | | |



| | | | | | |
|-----------------------------|----------|---|--|--|--|
| Code: CLV | 27.3 ft. | 9 | | | |
| Observation: Lateral Active | | | | | |
| Remarks: | | | | | |



| | | | | | |
|---|----------|--|--|--|--|
| Code: TIEU | 65.3 ft. | | | | |
| Observation: Inspection Ends at Upstream MH | | | | | |
| Remarks: | | | | | |



F14




Scaled Plot

505-341-0109

| | | | | | |
|---------------------------------|---------------------------------|-------------------------------------|------------------------|----------|--|
| Pipe ID F14 | City | Street MURRAY HOLLADAY RD | Shape | Map #1 | Basin |
| US Manhole F14 | Section Length 20.951 | Year Laid | Material | | Section Type |
| DS Manhole F13 | Inspected Length 65.3 | Year Renewed | Depth US N/A | Depth DS | Joint Leng... Diameter 18 |

| | | | | | |
|----------------------------|-------------|----------------------|------------------------------------|--------|--|
| Cleared | | Situation | | Reason | |
| Date 20181012 | Clean Date | Weather | | Remark | |
| Start Time 14:01 | | | | | |
| Operator KEVINT | Customer | Truck 4165 | Inspection Dir. UPSTREAM | Info | |
| Operator Comment | P.O. Number | Present | Flow Control | Camera | |



* = clock positions adjusted automatically for reverse inspection