




Left Plot w/ Pics

505-341-0109

Pipe ID N120-83	City	Street WANDER CIR 4800 S	Shape	Map #1	Basin
US Manhole N120-83	Section Length 52.035	Year Laid	Material PRC	Section Type	
DS Manhole N120-80	Inspected Length 149.8	Year Renewed	Depth US 7	Depth DS	Joint Leng... Diameter 8
Cleaned	Situation		Reason		
Date 20181009	Clean Date	Weather		Remark	
Start Time 11:26					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



N120-83

Distance: Pos: Val 1 / 2 : % : Gallons:



Code: TIBU	0.0 ft.				
Observation: Inspection Begins at Upstream MH					
Remarks:					



Code: TIED	149.8 ft.				
Observation: Inspection Ends at Downstream MH					
Remarks:					

N120-80




Scaled Plot

505-341-0109

Pipe ID N120-83	City	Street WANDER CIR 4800 S	Shape	Map #1	Basin
US Manhole N120-83	Section Length 52.035	Year Laid	Material PRC	Section Type	
DS Manhole N120-80	Inspected Length 149.8	Year Renewed	Depth US 7	Depth DS	Joint Leng... Diameter 8

Cleared		Situation		Reason	
Date 20181009	Clean Date	Weather		Remark	
Start Time 11:26					
Operator CODY	Customer	Truck 4161	Inspection Dir. Downstream	Info	
Operator Comment	P.O. Number	Present	Flow Control	Camera	



* = clock positions adjusted automatically for reverse inspection

Scale: 1:800